

HISTORIC PRESERVATION COMMISSION STAFF REPORT

APPLICATION:	Special Review	AGENDA ITEM:	AR-5	
PREPARED BY:	lli Lobaco Associate Planner	MEETING DATE:	July 23, 2014	
SUBJECT:	Special Review of Demolition of Pre-1940's Residential Structure 152 North Primrose Avenue			
APPLICANT:	Todd Bowden 212 West Foothill Boulevard Monrovia, CA 91016			
REQUEST:	Demolition of pre-1940's residence			
ENVIRONMENTAL	DETERMINATION:	Ministerial Action PRC §21	080(b)(1)	


BACKGROUND: On July 3, 2014, the owner of 152 North Primrose Avenue submitted an application to demolish the house at this location. According to County Assessor information, the home was built in 1936 and is therefore subject to the residential demolition ordinance which applies to residential structures in residential zones that were built prior to 1940.

DISCUSSION: According to current Tax Assessor information, the existing 780 square foot stucco-sided single-story residence was built in 1936 and has two bedrooms and one bathroom. City building permits indicate that permits exist to 1912. In regards to permits for the existing rear structure, a sleeping porch was added to the rear of the house in 1946.

On the 1927 Sanborn Maps, two dwellings are shown along with a detached accessory structure between them. Permits on file show that there once existed a larger front unit. In 1946 a room and one car garage



was added to the front of the front unit. In 1958 the rear section of the front house was demolished leaving the one-car garage with attached room.



The home is stucco sided with no significant architectural features. Windows have been replaced and it appears the rear porch area has been enclosed without a permit and has not been painted. The owner did submit information from the City Directories regarding persons who lived in the home. Those names include Edward Siegel (1948) F. W. Fetters (1948-1968). City permits show permits by owners A. F. Squire (1920-1921) and G. E. Fetters (1946, 1957 and 1958). The home was then owned by the Wilkerson family from 1979 until its recent sale to the current owners.

The home is not part of the draft Historic Resources Survey of 2004. Due to its lack of architectural integrity and not having any known association with persons of historical interest, Staff has assigned it a California Historic Resource (CHR) Status Code of 6Z. A 6Z status is assigned to properties that do not meet any of the criteria required for landmark designation.

The City's demolition ordinance puts up to a 120-day hold on the issuance of a demolition permit for affected structures. Once the City receives an application for demolition, the 120-day period begins, and the review is then set for the next available agenda of the Historic Preservation Commission. This request was received on July 3, 2014. The date of the Historic Preservation Commission meeting marks the 20th day from the date of application.

Staff recommends that the Historic Preservation Commission find that the residence at 152 North Primrose Avenue is not eligible for landmark status and may be demolished. Further, staff is recommending that the Commission end the 120-day hold. If the Commission concurs with this recommendation, then following the public meeting then the following motion is appropriate:

Approve the DPR Form with a Status Code of 6Z finding that the residence at 152 North Primrose Avenue does not have architectural or known historic value that meets the criteria for local landmark status and waive the 120-day hold.

City of Monrovia Department of Community Development PRIMARY RECORD			HRI # Trinom	Primary # HRI # Trinomial CHR Status Code 6Z	
		Other Listing Review Code			Date
Page	<u>1</u> of <u>2</u>	*Resource Name or #:	152 North Primrose Aver	nue	
P 1	Other Identifie	er:			
*P2	Location:	Not for Publicatio	n 🛛 Unrestricted		
	a. County:	Los Angeles			
	c. Address:	152 North Primrose Avenu	е	City: Monrovia	Zip: 91016
	e. Other Loca	tional Data: APN # 851	9-021-005		

P3a Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The 780 square foot stucco-sided single-story residence was built in 1936 and has two bedrooms and one bathroom. According to City Permits on file, an addition was added to the rear in 1946 that included a sleeping porch. At that time the front structure (which was larger) had a living room and one-car garage added to it. The rear of the front house was demolished in 1958. The remaining home is stucco sided with no significant architectural features. Windows have been replaced and it appears the rear porch area has been enclosed without a permit and has not been painted.

P3b Resource Attributes: (List attributes and codes) HP2. Single family property

		(, 6 6			
*P4	Resources Present:	🛛 Building	Structure Structure	Object	Site	District	Element of District	Other
P5a	Photograph					P5	b Description of Photo	: Front,
_						Ju	v 2014	



P 6	Date Constructed:	1936
	Source: LA County A	Assessor
	wden Development	
212	wden Development 2 West Foothill Boulevard nrovia, CA 91016	d
Bov 212 Mor	2 West Foothill Boulevard	d

P11 Report Citation:

Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Other (List):

City of Monrovia Primary # ______ Department of Community Development HRI # _______ BUILDING, STRUCTURE, AND OBJECT RECORD Trinomial _______

Page 2 of 2 *Resource Name or #: 152 North Primrose Avenue

- B1 Historic Name: None
- B2 Common Name: None
- B3 Original Use Single-family Residence
- B4 Present Use Single-family Residence
- **B5** Architectural Style Bungalow

B6 Construction History (Construction date, alterations, and date of alterations)

- 1912 Sewer permit
- 1920 Electrical and plumbing permits for a garage
- 1921 Addition
- 1936 Tax Assessor built date
- 1940 Sewer permit for rear house
- 1946 Add sleeping porch on rear of rear house, and one room and garage to front house
- 1958 Rear section of front house demolished and only a one car garage and living room remain on front house

B7	Moved: No	Date Moved	Original Location	

B8 Related Features: Detached garage at front of property also has no known historic or architectural significance

B9a	Architect:	Unknown		b. Builder:	Unknown
B10	Significance:	Theme:	None	Area:	Monrovia
	Period of Sign		None		HP2 - Single Family Property

Discuss importance in terms of historical or architectural context as well as integrity.

The dwelling does not appear eligible for listing in the National Register, California Register, or for local designation due to lack of sufficient integrity or significance.

B11 Additional Resource Attributes:

B12References:
Sanborn Maps
City Directories
City Building PermitsB13Remarks

B14 Evaluator/ City of Monrovia Date July 2014 Sketch Map with north arrow: